


Quality Assurance Project Plan Addendum USAEC PFAS Site Inspection Picatinny Arsenal, NJ

Figure 6 AOPI Former WWTP Facility Proposed Sampling Locations





AOPI Location

Approximate Location of Leach Fields

- ◆ Well
- Well (Abandoned / Not Located)
- Assumed Groundwater Flow Direction

Groundwater Sampling Locations

Proposed Sample Location for SI

Surface Water Sampling Locations

Proposed Sample Location for SI

Soil Boring Sampling Locations

Proposed Sample Location for SI

Note:

Accessibility of soil sample location will be determined in the field.

Coordinate System: WGS 1984, UTM Zone 18 North